DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: [illegible] APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 460 gpd DATE EVALUATED: 6-29-05
LOCATION OF SITE: Lot 10 Village at Valley Ranch PROPERTY SIZE: ___
WATER SUPPLY: ☐ Private ☒ Public ☒ Well ☐ Spring ☐ Other ___ PROPERTY RECORDED: ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	1-K	0-8	gr fr sl fri						
		8-27	ABK fr c	fr SSSP SOP	few-common gray/brown mottles				.25
		27-49	wk SBK yr cl	fr SSSP					
2	2K 3-10	0-5	wk SBK brn sl	fr SSSP					
		5-27	ABK R c	fi SSSP	common gray brn mottles				.25
		27-57	wk SBK yr cl	fr SSSP					.3 72"+
3		0-21	wk sbk brn sl	fr SSSP					
		21-38	wk SBK RC	fr SSSP SOP					
		38-54	wk SBK yr sd	fr SSSP	common SAP/w. wet				.3
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	LPPBPS	LPPBPS
Site LTAR	.25	.25

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: [signature]
OTHER(S) PRESENT: Paul Pennington