DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Needham / Bruce Dail — APPLICANT: _____
ADDRESS: _____ — APPLICATION DATE: _____ — DATE EVALUATED: 3-13-96
PROPOSED FACILITY: Duplex Apt — PROPOSED DESIGN FLOW (.1949): 480 gpd — PROPERTY SIZE: 30,000 ft²
LOCATION OF SITE: Lot 6 Mallard Pines — PROPERTY RECORDED: NO
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LAND-SCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 4-6%	0-5	gr sl sub c bon	sl fr 1:1					-3
		5-24	SBK ec	fi sp 1:1					
		24-48	MSBK RCL	fr SSp 1:1					
2	L 4-6%	0-5	gr sl	fr NP					-3
		5-10	SBK R-BRN SCL	fr 1:1					
		10-23	SBK RC	fi, sp 1:1					
		23-48	MSBK RCL micaceous, few gravel & cobble wetter	fr SSp 1:1					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____