DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 1-22-03
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 23 Whispering Pines PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

(#6) 0-4 gr-wksebk brn scl fr sssp → LPP .125
4-27 mfsbk RC fr sp scpp Common-many yb mottles
but 27-49 wk fsbk RCL fr sssp 2 manganese
few ch 2

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-6	gr brnscl	frsssp					
		6-49	mfsbk/wk RC	fr sp few common yb mottles					.25
2		0-9	wsbk dscl	fr sssp					
		9-34	mfsbk RC/cl						
		34-61	mf mabk RC		- common	SAP/ common YB mottles fri 2/3 chroma			.3 @ 34"
3	5-8% L	0-4	gr brn scl	frsssp					
		4-24	mfsbk RC	fr sp					.3
		24-59	mfsbk cl	frsssp common mica sap					
4		0-5	wsbk dscl	fr sssp					
		5-65	mfsbk RC	fr ≤ p	- many YB mott/few 2c chroma @ 25"				.05 LPP. to (4)

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	pm 25% Red	LPP
Site LTAR	.25	.125

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS for 3BR using pm 25% Red w/ LPP repair
EVALUATED BY: DMH
OTHER(S) PRESENT: _____

COMMENTS: _____

#5 0-23 wk sbk brn scl fr sssp
23-37 wk sbk yb brn scl fr sssp
37-60 MB yb-yRC
ch 2 @ 43"

dutchtown
.25 @ 30" 4 borings