WASTEWATER SECTION

COUNTY:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

ER: Dienst APPLICANT:

RESS: APPLICATION DATE: DATE EVALUATED: 7-16-02

POSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 480gpd PROPERTY SIZE:

CATION OF SITE: Lot 5 The Preserve PROPERTY RECORDED:

TER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other

ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
#5 TCS	0-15	wk fgr bk brn scl	fr sss p					
	15-27	wk fsbk R scl	fr sss p sp					.3
	27-36	wk fsbk yr scl	fr sss p	common wet sap				
	36-48	massive mottled sl sap	fr nss p					
(2) 9% L	0-8	gr brn scl	fr sss p					
	8-42	m fsbk rc	fr sss p sap					.3
	42-54	wk fsbk yr cl	fr ss p	common wet sap				
	54-66	massive mottled sl sap	fr sss p					
(3)	0-20	gr wk fsbk brn sl	fr sss p					
	20-42	wk fsbk R sl	fr fr sss p sap					.3
	42-56	massive mottled yr sl sap	fr sss p					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)	PS	PS
tem Type(s)	Conv 25% Red	LPP PBPS
LTAR	~.3	~.3

OTHER FACTORS (.1946):

SITE CLASSIFICATION (.1948): PS

EVALUATED BY: DM Jongsma

OTHER(S) PRESENT: Paul Dennington