ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Bonanza Dev. MLOP, LLC APPLICANT: Same
ADDRESS: 816 E RSR APPLICATION DATE: 5-9-05 DATE EVALUATED: 5-9-05
PROPOSED FACILITY: Comm PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 30,000
LOCATION OF SITE: PROPERTY RECORDED: No
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other Comm Well
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L/H ~62	0-9	SL/ms	fr SS/SP	54YR 6/6 9-32	54"	C incl 52+		PS .25-.3
		9-32	C - SBK	fr S/P					
		32-54	CL - MSBK	fr SS/SP					
				(SE)					
2	H/M ~62	0-9	SL - MS	fr SS/SP		58"			PS .2
		9-38	SC - SBK	fr S/P					
		38-58	CL - SBK	fr SS/P					
				(SE)					
3	L/K ~62	0-8	LS SL - MS	fr SS/SP	5YR 6/6 8-32	52"			PS .25
		8-32	C SBK	fr S/P					
		32-52	C-CL SBK	fr SS/SP					
				(SE)					
4	H/M ~60	0-16	C ABK	fr S/P			C incl 16+		PS .2
		16-55	CL SBK	fr SS/SP					
				(SE)					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
vailable Space (.1945)	PS	PS
ystem Type(s)	25%	PAN
te LTAR	.25	.25

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948): PS
EVALUATED BY:
OTHER(S) PRESENT: Scott Need Kan