DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
Lot 13 for ON-SITE WASTEWATER SYSTEM

OWNER: Village Rd. Lots 2 Pools APPLICANT: Brandon Dev. Co.
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-31-
PROPOSED FACILITY: House PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: _____
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

Lot 13

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	C ~10%	0-20	mfsk c	fr ss/so	RED 4/1 M	48+	INJ SNP 30%		PS - 3
		20-48	wssk cl	fr ss/so					
2	C ~10%	0-5	sl sl	fr ss/so	grayish brown, f 2.5 to 36+	~36"			PS - 25 to 36"
		5-43	wssk sl	fr ss/so					
3	6-12% 8-12% H/F	0-12	wksbk brn sil	fr ss/sp	236"				.025 to 35"
		12-35	mfsbk brown c	fr ss/sp/sp					
		35-D	Weathered common	fri sso/sp and sap					
4	6-12% F	1-36	wksbk brown	fr ss/sp/ common manganese conc	24"				.25 to 36"
		36-47	mfsbk brown	fr ss/sp/ common manganese conc					
			root channels common	but open channels					
			and sap/ other	gravel mottles					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: PSD
OTHER(S) PRESENT: _____

Approved ICHD

SECTION
SECTION
GUTTER SECTION

SCALE: 1" = 50'

30,000
Lot 27 is sm
Lot 28 is well lot, 1

