DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ___ OF ___
PROPERTY I.D.#: ___
PROPERTY RECORDED: ___
COUNTY: ___

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Richard Bond OWNER: X AGENT: ___ PHONE: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: 3/13/97
PROPOSED FACILITY: ___
PROPERTY SIZE: ___
LOCATION OF SITE: Lot 223 Fairway Estates
WATER SUPPLY: On-Site Well X Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring X Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	CV L 30%	0-7	sbk / scl	FR NS NEXP NP	S	S	PS	S	
		8-14	sbk / hcl	FR NS SEXP SP	S				.3
		15-30	wk sbk / cl	FR S SEXP P	S				
		31-48	sbk / lt. c l	FR S NEXP SP	PS				.3
2	consistent with E1				moist in bottom				
3									
4									
5									

AVAILABLE SPACE (.1945) PS SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: .3
EVALUATED BY: Sparks OTHER(S) PRESENT: Buddy Bafford, Mrs. Bond
COMMENTS: Very moist in bottom of boring probably just from soil moisture — no mottling noted