4636409207

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR James M. Duckworth DATE 8/14/79 PERMIT NO. 290

PHONE: Business Brawley School Rd. Home


LOCATION 1100 TL 1 1/2 Stutts Rd TR into Marina Village (across from the Tank) +90 to end of PAVED Road on left S. R. No.

SUBDIVISION NAME ~~Lake Norman~~ Marina Village LOT NO. SECTION OR BLOCK NO. 9

House (✓) Mobile Home ( ) Business ( ) Other

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Clay loam	
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	80 MPI +	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	4-6%	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	UNKNOWN	
Lot Area ~3/4 Acre			Rock or other impervious formations	NONE OBSERVED	



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 750 Linear Ft. 250
Depth of Stone in Lines 16"+

Water Supply: Individual (✓)
Public ( )

Installed by J. J. Ervin

IMPROVEMENTS PERMIT BY David R. Hinson

COMMENTS:

CERTIFICATE OF COMPLETION BY Fred A. Clement, RS DATE 8/14/79

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR James M. Duckworth DATE 5-28-79 PERMIT NO. 166

PHONE: Business _____ Home _____


LOCATION 1100 TL on 1112 TR into Marina Village and go to end of paved rd. on left. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2
Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )
Lot Area ~ 3/4 AC.

Character & Porosity of Soil Clay loam
Percolation Rate 50 mpi +
Topography 4-6%
Depth to Water Table unk.
Rock or other impervious formations none obs.



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 750 Linear Ft. 250
Depth of Stone in Lines 16"+
Water Supply: Individual (✓)
Public ( )

Installed by J. J. Ervin

IMPROVEMENTS PERMIT BY David R. Henson

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold