DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mike Fox APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 12/14/98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: 1
LOCATION OF SITE: Stutts Cove, Lot # 25 PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Pit #1	0-12	Brw SCL GR FR						PS .3
		12-30	Rd/Brn C M wSBK		SBK S-SSSR SE, FI-FR				
		30+	Rd/Brn C M wSBK		Saprolite				
			Water in pit at 30"						
2	Pit #2	0-9	Brn SL GR FR						PS .3
		9-32	Rd/Brn CL M wSBK		S-SSPR SE, FI-FR				
		32+	Brn/Yel LSAP						
3	Below 50' Buffer Stake	0-12	Brn SCL GR FR						PS .3
		12-32	Brn CL wSBK		S-SSPR SE, FI-FR w/ some low Chroma Mottles starting at 30"				
		32+	Brn/Rd C M wSBK						
4		0-12	Brn SCL GR FR						PS .3
		12-40	Rd/Brn C M wSBK		S-SSPR SE, FI-FR				
			Water in Bottom of Pit at 40"						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____