DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Forney Dev Co. APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 2-12-98
PROPOSED FACILITY: Duplex Lot PROPOSED DESIGN FLOW (.1949): 440 gpd PROPERTY SIZE: ~80'x110'
LOCATION OF SITE: Lot 3 R (Gate Hill Extension) Lot 3Y PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut Loamy
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS 1943 SOIL DEPTH	OTHER PROFILE FACTORS 1956 SAPRO CLASS	OTHER PROFILE FACTORS 1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	S 12-18%	0-3	gr brn scl	fr sl sticky					.25
		3-24	sdy clay loam	fr sl sticky					
		24-48	mott sdy clay	fr sticky					
			many yellow mottles from depth approaching Hz 3						
			1.0						
2	H	0-7	gr brn scl	fr	P				maybe .25
		7-23	sdy clay loam	fr SO SW/mod					
		23-48	mott sdy clay loam	fr sst					
			many g-R/y-brn mottles, few/fresh gravel						
			mod SW in this Hz drainage mottles						
3		0-7	sdy lo	fr SO sst					PS .3
		7-43	sdy clay loam	fr sl sticky					
		43-48	mottled gr/y	fr sticky					
4	L or mk lo	0-23	sdy lo red	fr sl sticky					PS .3
		23-48	mottled red clay loam	fr sticky					
			few-many y-brn mottles						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____