ON-SITE WASTEWATER SECTION

COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Ray Shot APPLICANT: _____

ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 8-5-99

PROPOSED FACILITY: 1 SFR PROPOSED DESIGN FLOW (.1949): 3 bed PROPERTY SIZE: 2 AC

LOCATION OF SITE: 1434 Connecticut PROPERTY RECORDED: yes

WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | 1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE | 1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR | 1943 SOIL DEPTH | 1956 SAPRO CLASS | 1944 RESTR. HORIZ. | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | L-S 0-5% | 0-32 | SaLo fine sand, single grain, loose, few fine roots | | | | | | I .5 .3 |
| | | 32-48 | mottled SaLo gr. cl. fr. sss, pss few gravel, few coarse roots | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 2 | S/depression 2% | 0-9 | SaLo, loose, fine | | | | | | I .5 .3 |
| | | 9-48 | SaLo, loose, fine, few fine gravel, few coarse roots | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 3 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____