DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mike Fox APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 12/8/98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Stutts Cove Lot #12 Stutts Cove PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other Turbyfill
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1943 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1941 RESTR HORIZ	PROFILE CLASS & LTAR
1	Pt	0-12"	Brw SCL GR FR						PS .3
		12-48"	Rd/Brw C M-MSBK	SS,SP,SE,F-FR					
2	Behind House Near R.R Corner Pit	0-13"	Brw SCL GR FR						PS .3
		13-44"	Rd/Brw C M-MSBK	SS-SS,SP,SE,F-FR w/ Some Rd/Brw relic motle S > 37"					
3	Pt	0-14"	Brw SCL GR FR						PS .3
		14-36"	Rd/Brw C M-MSBK	SS-SS,SP,SE,F-FR w/few Inclus					
		36-48"	Rd/Brw C M-MSBK	SS,SP,SE,FR w/few SAP Inclus					
4	Pt 2	0-25"	Brw SCL GR FR						PS .3
		25-32"	Rd/Brw C M-MSBK	SS,SP,SE,F-FR w/Few Inclus of SAP					
		32-48"	Rd/Brw C M-MSBK						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____