DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mike Fox APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 12/9
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Stotts Cove Lot #49 Stotts @ PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other Turby Fill
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	(1940) LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Pit #1 RR Cove	0-8"	Rd/Brn SCL	wSBK-massive					PS .35
		8-UR	Rd/Brn C/CL	m-wSBK SS, SP, SE, FI-FR w/ few to many Stl rocks + Some W Rock					.3
2	Pit #2 Flat Area	0-6	Brn SCL	wSBK-massive					PS
		6-20	Rd Brn C/CL	mSBK SS, P, SE, FI					
		20-40	Rd/Brn C/CL	wSBK SS, SP, SE, FI-FR w/few to many SAP Lab					.3
		40-50	SAP						
A	Auger In Front	0-10"	Brn SCL GR FR						PS
		10"-48"	Rd/Brn C/CL	m-wSBK SS, SP, SE, FR w/ some Mica					.3
B	Auger In Front	0-6"	Brn SCL GR-wSBK		SS, SP, SE, FR				PS
		6"-36"	Rd/Brn C/CL	m-wSBK SS, SP, SE w/ common Mica Flakes					.3
		36-UR	CL & LSAP mix						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____