DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: 4/6364205 136935
COUNTY: ___

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Cardena Builders
ADDRESS: ___
PROPOSED FACILITY: House
PROPOSED DESIGN FLOW (.1949): 480
LOCATION OF SITE: ___
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut

APPLICATION DATE: 6/17/00
DATE EVALUATED: 6/27/00
PROPERTY SIZE: 4
PROPERTY RECORDED: ___
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-52 | CLWSBK | SSSPSSP | fr | 52 | | | 3 |
| 2 | | 0-7 | SCWSBK | SSSPSSP | fr | 52 | | | 3 |
| | | 7-52 | CWSBK | SSSPSSP | fr | | | | |
| 3 | | 0-7 | CLWSBK | SSSPSSP | fr | 52 | Bad tpo | | 3 |
| | | 7-52 | SCWSBK | SSSPSSP | fr | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | 1600/2500 | |
| System Type(s) | 600 Pipe Pad | |
| Site LTAR | .3 | |

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): RS
EVALUATED BY: Kelly Cook
OTHER(S) PRESENT: ___

COMMENTS: ___