DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ *of* ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Banks #3 PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-38	c-cl sbk	A-ssp					A 0.3
		38-53	sl-l sgp m	fi ss sp					
2		0-50	c-cl sbk	fi ss sp					A 0.3
			Incl sap (a 32"						
3		0-8	sl sbk	fi ss sp					A 0.3
		8-58	c sbk	fi ss sp					
			Incl sap 0 to 8						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____


40'30" Panel
LPP
Panel Repair
System
EZ flow
Shallow Conv.
System
LPP dist.
N 10°27'49"
127.26'
152.39'
Yellow 30'
Red 35'
Pink 43'
Blue 37'
Yellow 45'
Red 52'
Pink 56'
Blue 65'
Yellow 70'
Red 83'
Blue 33'
50'x60'
no bment
S 86°51'31" W
150.17'
50'
SETBACK
83'
well
C2
C3
L34
N 47°20'55" W
94'
Yello
Blue 9
Pink 10
Red 10
Yellow
Blu
C14
1" = 50'