DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: 122432
COUNTY: 4636-67-3763

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Applicant
OWNER: Vidal Toddz APPLICATION DATE 7-2-04
ADDRESS: 3324 E ORAIBI PHOENIX AZ 85050 DATE EVALUATED: 8-11-04
PROPOSED FACILITY: 4 BR HOUSE PROPOSED DESIGN FLOW (.1949): 480 PROPERTY SIZE: .46
LOCATION OF SITE: HUNTERS BLVD LOT 19 PROPERTY RECORDED: YES
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☒ Other COMMUNITY
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	10% LSS	0-12	sl wk gr	fr ns np ns p		>48"			PS .3
		12-24	cl wk sbk	fr ss sp ss p					
		24-40"	c med sbk	fi sp se p					
		40-48"	sl gr wk	fr ss sp se p					
2	10% LSS	ROCK @ 10"				/			US FLOATER ROCK
			FLOATER						
3	6% LSS	0-12"	cl wk sbk	fr ss sp ss p		48"			PS .3
		12-48"	c med sbk	fi sp ss p					
			few to many sap	inclusions < 50%					
		48"	ROCK						
4	6% LSS	0-12"	cl wk sbk	fr ss sp ss p		48"			PS .3
		12-48"	c med sbk	fi sp ss p					
			sap inclusions	few to many but < 50%					
			SAP > 50% @ 48"						

LSS 0-12 sl wk gr fr ss sp ss p
6% 12-48" c med sbk fi sp ss p
few sap inclusions < 50%

#5

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	YES	YES
System Type(s)	LP SUPPLIED	LP SUPPLIED
Site LTAR	.3	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: L. LOOK
OTHER(S) PRESENT: ___

COMMENTS: ___