9:30

IREDELL COUNTY HEALTH DEPARTMENT

12949 (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Marty Edwards DATE 6/11/91 PERMIT NO.

PHONE: Business Home 704-278-2004

LOCATION Peninsula Dr., Brawley TL on Stutts Rd., TL on Peninsula Dr. to end Cul de sac, lot on (R) with well closest to road S. R. No.

SUBDIVISION NAME Norman Shore LOT NO. 7 SECTION OR BLOCK NO.

House (✓) Mobile Home ( ) Business ( ) Other


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil A - clay-loam/clay - s on top
Percolation Rate 4
Topography 2-7% slopeing
Depth to Water Table > 45"
Rock or other impervious formations No

Lot Area 20,000 FT²

✓ Basement with Plumbing ____ Basement without Plumbing ____ No Basement



Size of Tank 1000 Gals.
Nitrification Field: Panel System
No. of Lines 2 @ 80'
Sq. Ft. 900 Linear Ft. 160
Depth of Stone in Lines
Water Supply: Individual (✓)
Public ( )
16" T+J PANEL SYSTEM

Installed by

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: x Marty Edwards

IMPROVEMENTS PERMIT BY Wesley Sparks RS,

COMMENTS: Shallow trenches no deeper 36" to trench bottom. Trenches on slope contour.

CERTIFICATE OF COMPLETION BY DATE

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold