Type 4 inspection 12-5-01 mb

IREDELL COUNTY HEALTH DEPARTMENT 4636-73-8859

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Donald & Ann Horte DATE 7/22/86 PERMIT NO. 000328

PHONE: Business _____ Home _____

LOCATION Spring Run Drive off Canvasback

_____ S. R. No. _____

SUBDIVISION NAME Spring Run LOT NO. 12 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other Septic System on Easement in Melton Head Golf Course

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes (✓) No ( )

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area ≈ 3/4 acre

Character & Porosity of Soil Clayey


Percolation Rate 2.4 gpd/sq ft 2-40 min

Topography Gently

Depth to Water Table 4'+

Rock or other impervious formations None Noted

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1500 & 1000 gallon pump Gals.

Nitrification Field:

No. of Lines 2 75' lengths of 16" Panels

Sq. Ft. _____ Linear Ft. _____

Depth of Stone in Lines Sand

Water Supply: Individual ( )

Public (✓)

Installed by Wilford Bridges

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Joseph R Sheets RS

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Joseph R Sheets RS DATE 7/22/86

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold