* Attention Inspection Dept - See Comments

IREDELL COUNTY HEALTH DEPARTMENT

463674 1845

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Allen Brawley DATE 6-25-82 PERMIT NO. 192

PHONE: Business _____ Home _____

LOCATION #100 To 1179 TR 2nd Paved Sty TL Billy Joe's Blind TR Dirt Sty Run widens Neel Acres ON left where Road narrows then S. R. No. _____


SUBDIVISION NAME _____ LOT NO. 1 SECTION OR BLOCK NO. _____

House (X) Mobile Home ( ) Business ( ) Other Addition to house of 2 bedrooms w/Addition 3

No. Bedrooms 3 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (X)	Character & Porosity of Soil	Clay loam
Auto. Dishwasher	Yes ( )	No (X)	Percolation Rate	30-45
Auto. Wash. Machine	Yes (X)	No ( )	Topography	10-15%
Site Suitable	Yes (X)	No ( )	Depth to Water Table	42"
Lot Area ± 3/4 Acre			Rock or other impervious formations	None Observed

_____ Basement with Plumbing _____ Basement without Plumbing X No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 4
Sq. Ft. 150 Linear Ft. 250
Depth of Stone in Lines 16

Water Supply: Individual (X)
Public ( )

Brawley Court.

Installed by Owner / Moore Suttle

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY David Hinson

** COMMENTS: Existing system to be disconnected before final inspection / approval to be given

CERTIFICATE OF COMPLETION BY Fred Clemmer DATE 6-25-82

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold