DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Hammock #1 PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed (5) 0-12 scl 12-55 C PS 0.3

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	SFE Lot 4	0-10	scl sbk	frssp					PS 0.5
		10-42	c-cl sbk	frssp					
		42-55	cl sbk	frssp					
2	SFE Lot 4	0-8	scl sbk	frssp					PS 0.3
		8-55	c-cl sbk	frssp					
			Saw Tooth Sand 42"						
3		0-10	scl sbk	frssp					PS 0.3
		10-33	c sbk	frssp					
		33-41	cl sbk	frssp					
4		0-15	scl sbk	frssp					PS 0.3
		15-55	c-cl sbk	frssp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____


SEPTIC ESMT.
LOT 4
P.MANIFOLD
C8
N 07°12'50" E
100.77'
Red 34' Extra
Yellow 67' repair
Blue 110' repair
Pink 150'
Red 150'
Yellow 140' repair
L43
L42
L41
L40
L39
L38
C22
91'
L37
L45
L35
50'x50'
N 74°06'40" W
57.81'
Red 150'
Yellow 150'
Blue 100'
Pink 100'
GRAPHIC SCALE
1" = 50'
50 0 50 100
N 78°24'15" W
207.71'
L8
L7
L6
L5
L4
L3