DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____


SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Hammock rd: 1 PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed (5) 0-12 scl 12-55 C K 0.3

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LOT 4 SFE	0-10	scl sbk						PS .25
		10-22	c-cl						
		22-33							
2	LOT 4 SFE	0-8	scl sbk						
		8-55	c-cl sbk						
3	LOT 1	0-10	scl sbk						
		10-33	c sbk						
		33-41	cl sbk						
4	LOT 1	0-15	scl sbk						
		15-55	c-cl sbk						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


SEPTIC ESMT.
LOT 4
P.MANIFOLD
C8
N 07°12'50" E
100.77'
Red 34' Extra
Yellow 67' repair
Blue 110' repair
Pink 150'
Red 150'
Yellow 140' repair
L45
L35
L37
C22
91'
L38
L39
50'x50'
L43
L42
L41
L40
Red 150'
Yellow 150'
Blue 100'
Pink 100'
1
N 74°06'40" W
157.81'
69'
N 78°24'15" W L 207.71'
GRAPHIC SCALE
1" = 50'
50 0 50 100
761 CONTOUR
L4
L3
L5
L6
L7
L8