IREDELL COUNTY HEALTH DEPARTMENT 4636773619

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR George Brawley DATE 11-24-82 PERMIT NO. 376

PHONE: Business _____ Home _____

LOCATION Hwy 21 to 1179 to Amity Rd. to Buffalohead Dr. 3rd house from end (Cul-de-sac) on left

SUBDIVISION NAME Mallard Head LOT NO. 26 SECTION OR BLOCK NO. 1

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2½


Garbage Disposal Unit	Yes	( )	No	(✓)
Auto. Dishwasher	Yes	(✓)	No	( )
Auto. Wash. Machine	Yes	(✓)	No	( )
Site Suitable	Yes	(✓)	No	( )

Lot Area 120000 Sq Ft

Character & Porosity of Soil clay loam B 18-24"
Percolation Rate 4
Topography 6-8%
Depth to Water Table 72+"
Rock or other impervious formations 72+"

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement

2 systems, each



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 5
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual ( )
Public (✓)
Community Well

Installed by A J Erwin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Holding chamber and solids pump to be installed for basement plumbing.

CERTIFICATE OF COMPLETION BY David R. Hyman

EXISTING SYSTEM CHECKED BY: _____ DATE 11-24-82

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS. DATE _____

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold