4636775164

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Randy Ruckton DATE 5-6-87 PERMIT NO.

PHONE: Business Home

LOCATION 1100 TR 1179 (Canvasback) TR Old Squaw Trail at end of Cul-de-Sac on left S. R. No.

SUBDIVISION NAME Mallard Head LOT NO. 48 SECTION OR BLOCK NO.

House (✓) Mobile Home ( ) Business ( ) Other


No. Bedrooms 3 No. Bathrooms 3

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Lot Area 20000 ft² +

Character & Porosity of Soil clay
Percolation Rate 2-4
Topography 2-6%
Depth to Water Table 24+
Rock or other impervious formations none obs.

___ Basement with Plumbing ___ Basement without Plumbing ✓ No Basement



2 Systems
Front (Kitchen & Washer)
Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 450 Linear Ft. 150
Depth of Stone in Lines 12"

Water Supply: Individual ( )
Public (✓)
Community Well

Installed by J.R. Bowles

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed:

Back System (Bathrooms)
1000 gal tank
~200'+ (600 ft²)
2 ditches ~3'x100'

IMPROVEMENTS PERMIT BY

COMMENTS:

CERTIFICATE OF COMPLETION BY Elaine R. Hinson, R.S. DATE 5-6-87

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold