DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Bryan Long APPLICANT: ___
ADDRESS: Webbed Foot Rd. 0 APPLICATION DATE: ___ DATE EVALUATED: 8/15/96
PROPOSED FACILITY: 3-2.5 PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: ___
LOCATION OF SITE: Canvas Creek TR Webbed Foot to End lot on R PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Front ~CC 3% R-L	0-13	sbk / vfr sl	FR S SP					
		14-25	sbk hscl	FI S P					
		26-35	wk sbk sexp sc	FI S P	FAINT 3% MOT.				.25
		36-41	sbk cl	FR S P					
		42-48	sbk c	FR S SP					.3
2	Rear Right +2%	0-10	sbk slc	FR SS SP					
		11-24	wk c	FI S P					
		25-32	sbk hcl	FI S SP					
		33-47	wk cl	FR S P					.25
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS MOD	MOPPANEL
System Type(s)	ILE	PAN
Site LTAR	0-30 .25	"

OTHER FACTORS (.1946): when recorded
SITE CLASSIFICATION (.1948): soil OK - house too large
EVALUATED BY: Sparks
OTHER(S) PRESENT: N/A