IREDELL COUNTY HEALTH DEPARTMENT 4636818841

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jeff Pelchat DATE Oct. 12, '87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 1100 TR 1179 (Canvasback) near Lake in curve on left S. R. No. _____

SUBDIVISION NAME Woodland Hills LOT NO. 36 SECTION OR BLOCK NO. 3

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Lot Area 20000 Sq Ft

Character & Porosity of Soil clay
Percolation Rate 35
Topography 2-6%
Depth to Water Table 3-4'
Rock or other impervious formations none obs

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12"
Water Supply: Individual ( )
Public (✓)

Installed by Owner

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

Back System
440 gal tank
120 lin feet

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY R. Hinson, R.S. DATE 10/12/87

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold