9501 IREDELL COUNTY HEALTH DEPARTMENT 4636819847

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Randal Clark DATE 2/1/89 PERMIT NO. 21A

PHONE: Business _____ Home _____

LOCATION (30 Highland Dr.) 1100 TL Canvasback TL at end. 2nd on left. S. R. No. _____

SUBDIVISION NAME Woodland Hills LOT NO. 35 SECTION OR BLOCK NO. 3


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2½

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil Existing
Percolation Rate _____
Topography _____
Depth to Water Table _____
Rock or other impervious formations _____

Lot Area existing
_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System NOT TO SCALE

Size of Tank existing Gals.
Nitrification Field:
No. of Lines existing
Sq. Ft. _____ Linear Ft. _____
Depth of Stone in Lines 12"
Water Supply: Individual ( )
Public (✓)
Community

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: NO SIGN OF SEWAGE EFFLUENT SURFACING AT THIS INSPECTION.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: Andre C. Pierce DATE 2/1/89

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold