DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Varga
ADDRESS: _____
PROPOSED FACILITY: _____ APPLICATION DATE _____
LOCATION OF SITE: Woodland Hills #39 PROPOSED DESIGN FLOW (.1949): 480 DATE EVALUATED: 3-7-06
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY SIZE: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed PROPERTY RECORDED: _____

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-25	2sbk/abk c	fr ss/sps e		48			PS .3
		25-48	1sbk cl						
2		0-10	1 gr l	fr ss/sps e		13			U
		10-13	sl sap						
		13	rock						
3		0-10	1 sbk cl	fr ss/sp		20			U
		10-18	1sbk sl	fr					
		18-20	1sbk scl	fr ss/sp					
		20	rock						
4		0-12	1sbk sl	vfr		34			U
		12-28	1sbk cl	vfr					
		28-34	1sbk c	fr ss/sp se					
		34	sl sap						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1938): [illegible]
EVALUATED BY: T. Melville
OTHER(S) PRESENT: _____

COMMENTS: _____