DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Lakeside Bungalows APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: ___
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: .46
LOCATION OF SITE: Lot 109 Mallard Head PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	(F) 3-5% L	0-7	SMSBK/cl	Fr SS-SP	R				
		8-26	MMSBK/C MIC	FR NEAP SS-SP	S/R				
		27-37	MFSBK/cl	FR SS-SP	/4R				
		38-48	MMSBK/cl MIC	WFR SS-NP	PS/4R	PS	—		.3
2	(R) 3% L	0-12	SMSBK/C	Fr SS-SP	PS/4R	PS	—		.3
		13-48	MMSBK	FR SS-NP					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	Ty 3	Ty 4
System Type(s)	25% Red	16" PPBPS
Site LTAR	.3	.3

OTHER FACTORS (.1946): Small lot
SITE CLASSIFICATION (.1948): ~PS

EVALUATED BY: Sparks
OTHER(S) PRESENT: Dave Smith, W. Dobson