Notarization of Surveyor

by these presents, that I (we)

I (we) are the ow[illegible] of the propert[illegible]
me
plat an[illegible]

DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Wesley Zdreston
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: _____ DATE EVALUATED: 11-1-07
LOCATION OF SITE: Lot #106 Mallard Head PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-15"	Rd/Brn C/C		m-w SBK SS,SP,SE FP				PS .3
		15-46"	Rd/Brn to Brn C/C		w SBK SS,SP,SE VFP				
			Few to many SAP Inclusions						
			Common Mica flakes						
			Very dry at bottom						
2		0-10"	Brn SiL GR FP						PS .3
		10"-36"	Rd/Brn C/C		m-w SBK SS,SP,SE FP				to 36"
		36-42	Rd/Brn to Gry/Brn		Gry/Brn CL SS,SP,SE FI RP				.25
			w/ many		Yel/Brn mottles				
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____