...SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Haus Builders APPLICATION DATE _____

ADDRESS: _____ DATE EVALUATED: 11/29/02

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

LOCATION OF SITE: Mallard Head Lot 104 PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Inter.	0-20"	Rd/Brn C/C	m-w SBK	S-SS, SP, SE,	FI-FR			PS .3 to 42"
		20-45"	Rd/Brn C	m-w SBK	SS, SP, SE,	FR w/ Few			
			to Many SAP		Indus & Common			Mica Flakes	
		42-48"	C/LSAP	mix					
2	Rear	0-6"	Brn SL	GR FR					PS .25 to .3
		6-40"	Rd/Brn to Yel/Brn C	J	m-w SBK S-SS, SP, SE,	FI-FR			
			Lw/ Few Mica Flakes &		SAP				
					Indus				
3	Inter.	0-23"	Rd/Brn C/C	m-w SBK	S-SS, SP, SE,	FI-FR			PS .3 to 40"
		23-40"	Rd/Brn C	m-w SBK	SS, SP, SE,	FR w/ Few			
			to many SAP	J	Indus also			Common Mica Flakes	
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____

COMMENTS: _____