PROPERTY ID #: _____
COUNTY: _____

ON-SITE WASTEWATER SYSTEM

OWNER: Geoffrey Bowen APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9/17/02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot #100 Mallard Head PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	In Back	0-6"	Rd/Brn to Brn	SCL	FR	FR/ER			PS
		6"-34"	Rd/Brn C/Cl m-w	SBK SS,SP/SE, FR w/ Few-to many SAP	Inclusa	Common	Mica Flakes		.3 to 34"
		34"-48"	Rd/Brn C/L	SAP mix					
2	In Front	0-10"	Rd/Brn C/Cl m-w	SBK SS,SP SE					PS .3 to 24"
		10"-24"	Rd/Brn C/L w	Few-to many SAP Inclus					
		24-36"+	L	SAP	some W	Rock			
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____