4436-87-8005

12608

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR E O Stephens DATE 10/3/91 PERMIT NO. 2K-9-A-77

PHONE: Business _____ Home _____

LOCATION 1100 - TL 1179 on right just past Squaw Trail

S. R. No. _____

SUBDIVISION NAME Mallard Head LOT NO. 77 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes (✓) No ( )

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Character & Porosity of Soil P- clay (firm - sticky)

Percolation Rate .3


Topography 4% +

Depth to Water Table 43"

Rock or other impervious formations none observed

Lot Area 20,000 FT²

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1250 Gals.

Nitrification Field:

No. of Lines 5 @ 40' x 3'

Sq. Ft. _____ Linear Ft. 200'

Depth of Stone in Lines _____

Water Supply: Individual ( )

Public (✓)

Installed by F J Ervin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Maximum trench bottom 28". Lines installed on slope contour.

CERTIFICATE OF COMPLETION BY Wesley Sparks RS. DATE 10/3/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold