DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Ryon/West Dev.
ADDRESS: _____ APPLICANT: _____
PROPOSED FACILITY: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/30/05
LOCATION OF SITE: Lot #2 Josh Acres PROPOSED DESIGN FLOW (.1949): 480 gpd PROPERTY SIZE: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

Aqua Source

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | Initial ☆ | 0-2" | Brw to Rd/Brw SCL | | | | | | PS .3 |
| | | 2"-15" | Rd/Brw CL | m SBK SS, SP, FI-FR | | | | | |
| | | 15-39" | Rd/Brw CL | m-w SBK SS, SP, SE, FR | | | | | |
| | | | few wd/brw relic mottles | | | | | | |
| | | Previous Soil Work done by ICHD | | | | | | | |
| 2 | Repair | 0-3 | SCL w/SBK | | | | | | PS .25 |
| | | 3-22 | Rd/Brw SCL | w SBK SS, SP, SE, FR | | | | | |
| | | 22-48 | Rd/Brw CL | m-w SBK SS, SP, SE, FR | | | | | |
| | | | w/ Common mica flakes | | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Space (.1945) | | |
| | | |
| | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____