DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Deborah Bowen APPLICATION DATE ___
ADDRESS: ___ DATE EVALUATED: 1-27-05
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: .589
LOCATION OF SITE: Brawley Sch Rd, TL Canvasback, on left ½ mi. PROPERTY RECORDED: ___
WATER SUPPLY: ❑ Private ❑ Public ❑ Well ❑ Spring ❑ Other ___
EVALUATION METHOD: ❑ Auger Boring ❑ Pit ❑ Cut
TYPE OF WASTEWATER: ❑ Sewage ❑ Industrial Process ❑ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	linear concave 4%	0-16	2f abk C	fr SS/sp SE		48			PS .275
		16-32	2f abk C+sap	fr SS/sp SE					
		32-48	1f abk C+sap						
2	4% Repair	0-36	1 sbk/abk C	fr SS/sp SE		48			PS .3
		36-48	1 sbk/abk C+sap						
3	linear 4%	0-40	1 abk/sbk C	fi SS/sp SE		48			PS .275
		40-48	1 abk/sbk C+sap	fr SS/sp SE					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	yes	yes
System Type(s)	Pond, gdr	panel pm
Site LTAR	.275	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Judy Melville
OTHER(S) PRESENT: ___

COMMENTS: ___

½-1 cm abk Regency Lake? more house 30' when deeded? prior '83