IREDELL COUNTY HEALTH DEPARTMENT 4036-89-7247

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR M. F. Couch DATE 7-22-83 PERMIT NO. 246

PHONE: Business _____ Home _____

LOCATION 1100 TL 1179 on left on corner of 1233 + 1179

SUBDIVISION NAME Regency Lake Village LOT NO. 14 S. R. No. _____ SECTION OR BLOCK NO. E


House ( ) Mobile Home ( ) Business (X) Other _____ Office Building for Mobile Homes

No. Bedrooms _____ No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (X)	Character & Porosity of Soil _____
Auto. Dishwasher	Yes ( )	No (X)	Percolation Rate _____
Auto. Wash. Machine	Yes ( )	No (X)	Topography Existing System
Site Suitable	Yes (X)	No ( )	Depth to Water Table _____
			Rock or other impervious formations _____

Lot Area Existing Lot Recorded before 1973

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank Existing 1000 Gals.

Nitrification Field: Existing

No. of Lines 3

Sq. Ft. 625 Linear Ft. 225

Depth of Stone in Lines 10"

Water Supply: Individual ( )
Public (X) H2O System

11-27-70

Installed by Wesson Septic Tank

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

System installed 11-27-70 Wesson Septic Tank, Shelby

IMPROVEMENTS PERMIT BY _____

COMMENTS: Existing System working ok at date of inspection Checked by T. Scoggins

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: Fred Clemmer DATE 7-22-83

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold