IREDELL COUNTY HEALTH DEPARTMENT 4636911771

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION 4636912737
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR B & B Builders DATE 2-20-81 PERMIT NO. 46

PHONE: Business Brawley School Home

LOCATION 1100 TL 1179 Canvasback round curve on Rt

S. R. No.

SUBDIVISION NAME Woodland Hills LOT NO. 2 SECTION OR BLOCK NO. 1

House (✓) Mobile Home ( ) Business ( ) Other


No. Bedrooms 3 No. Bathrooms 2½

Garbage Disposal Unit Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Lot Area 20,000 ft²

Character & Porosity of Soil clay loam
Percolation Rate 80 mpi
Topography 2-4%
Depth to Water Table 4'+
Rock or other impervious formations none obs.

✓ Basement with Plumbing ____ Basement without Plumbing ____ No Basement



Plot of System

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 750 Linear Ft. 250
Depth of Stone in Lines 16"
Water Supply: Individual ( )
Public (✓)

Installed by Richard Abernathy

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

Location of the proposed DECK addition does not appear to impact the existing on-site septic system or well.**NOTE: REPLACING EXISTING DECK

APPROVED
REHS Date: OCT 24 2014
ICHD-Environmental Health Division
#206528

IMPROVEMENTS PERMIT BY JAC

COMMENTS: MUST BE MIN 5' FROM SEPTIC

CERTIFICATE OF COMPLETION BY David R. Hinson DATE 2-20-81

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold