4636923301

07390

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Girdharlal Kothadia DATE Nov. 14, '89 PERMIT NO. 2G-19-A-130

PHONE: Business _____ Home _____

LOCATION 1100 TR 1179 TR Highland Drive 2nd House on Right past Highland Place S. R. No. _____

SUBDIVISION NAME Woodland Hills LOT NO. 30 SECTION OR BLOCK NO. 3

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 3

Garbage Disposal Unit Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site ~~Suitable~~ PS Yes (✓) No ( )

Character & Porosity of Soil Clay
Percolation Rate ~3
Topography Fairly
Depth to Water Table 4ft
Rock or other impervious formations none obs.

Lot Area ~20000ft²

✓ Basement with Plumbing (Pump chamber in basement) Basement without Plumbing No Basement



Size of Tank 1500 Gals.

Nitrification Field:
No. of Lines 6
Sq. Ft. _____ Linear Ft. 200'of
Depth of Stone in Lines 16" ~~Top~~
Water Supply: Individual ( ) panels
CW ~~Public~~ (✓)

Installed by Richard Abernathy

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: _____

CERTIFICATE OF COMPLETION BY R. B. Johnson, R. S. DATE 11-14-89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold