IREDELL COUNTY HEALTH DEPARTMENT 4636933331

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Sam Owens DATE 3-10-81 PERMIT NO. 67

PHONE: Business _____ Home _____

LOCATION 1100 N 1179 ~.8 mi TL @ Reynolds sign
Mtn Pt. on Rt.


SUBDIVISION NAME Woodland Hills LOT NO. 95 SECTION OR BLOCK NO. 4 S. R. No. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes (✓)	No ( )	Character & Porosity of Soil	clay loam
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	50 mpi
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	6-8%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4'+
Lot Area ~ 3/4 AC.			Rock or other impervious formations	none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 750 Linear Ft. 250
Depth of Stone in Lines 18"
Water Supply: Individual ~~(✓)~~
Public (✓)
Community Well
Installed by Wayne Dobson

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: System installed before house built.

CERTIFICATE OF COMPLETION BY David R. Hanson

EXISTING SYSTEM CHECKED BY: _____ DATE 3-10-81

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold