DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Art Pitt OWNER: ____ AGENT: ____ PHONE: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: 6/28/94
PROPOSED FACILITY: 3 bedroom SF Dwelling
PROPERTY SIZE: ____
LOCATION OF SITE: Lot 92, Woodland Hills
WATER SUPPLY: On-Site Well 1 Comm. Well ✓ Public ____ Other ____ EVAL. METHOD: Auger Boring ✓ Pit ____ Cut ____

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS	HORIZON LTAR
1	LS	0-5"	gr sab - scl	1:1 / fr			PS		.3
		5-18"	sab / c	1:1 / fi-vfi					
		18-44"	wksab / sicl	1:1 / fr-fi					
2									
3									
4									
5									

AVAILABLE SPACE (.1945) U.K. SITE CLASSIFICATION (.1948): PS pre.1956 SITE LONG-TERM ACCEPTANCE RATE .3
EVALUATED BY: D. Johnson OTHER(S) PRESENT: Charles Humphrey (Lake Const.)
COMMENTS: Majority of site unsuitable due to complex, gullied topography except area on front (street side) of site. * Lot recorded prior to 1983