IREDELL COUNTY HEALTH DEPARTMENT 4636945712

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR ROGER PELCHAT DATE 10/23/87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 1100 Lf on Canvasback, Lf on BROADBILL INTO WOODLAND HILLS LOT ≈ 200yds. on Left

SUBDIVISION NAME WOODLAND HILLS LOT NO. 51 SECTION OR BLOCK NO. 10 S. R. No. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 4 No. Bathrooms 2 1/2

| | | |
|---|---|---|
| Garbage Disposal Unit | Yes (✓) | No ( ) |
| Auto. Dishwasher | Yes (✓) | No ( ) |
| Auto. Wash. Machine | Yes (✓) | No ( ) |
| Site Suitable | Yes (✓) | No ( ) |

Lot Area ≈ 3/4 ACRES

Character & Porosity of Soil Clayey
Percolation Rate 0.4 gpd/ft²
Topography 2-4%
Depth to Water Table 4'+
Rock or other impervious formations Scattered surface rock

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement




Plot of System NTS

Size of Tank 1500 Gals.
Nitrification Field:
No. of Lines 5
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"
Water Supply: Individual ( )
Public (1)

Installed by F.J. ERVIN

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andrew C. Prince DATE 10/23/87

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold