4636-94-6603

IREDELL COUNTY HEALTH DEPARTMENT

10732

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

ENTERED

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Roger Pelchat DATE July 13, '90 PERMIT NO. 26-19-A-52

PHONE: Business _____ Home _____

LOCATION 1100 TL 1179 (Cannasback) TR Brookhill ~ ¼ mile on left S. R. No. _____

SUBDIVISION NAME Woodland Hills LOT NO. 52 SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2½

Garbage Disposal Unit	Yes	(✓)	No	( )	Character & Porosity of Soil SS clay
Auto. Dishwasher	Yes	(✓)	No	( )	Percolation Rate 40 35
Auto. Wash. Machine	Yes	( )	No	( )	Topography 4-8%
Site ~~Suitable~~ RS	Yes	(✓)	No	( )	Depth to Water Table 4'
					Rock or other impervious formations none obs.

Lot Area 20000 ft²

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 6
Sq. Ft. 1050 Linear Ft. 350
Depth of Stone in Lines 12"

Water Supply: Individual ( )
Public (✓ Iredell)

Installed by A J Erwin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE 7-13-90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold