4636974200

IREDELL COUNTY HEALTH DEPARTMENT

15147 IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR James R. Miller DATE Nov. 3, '92 PERMIT NO. 2K-18-A5

PHONE: Business _____ Home _____

LOCATION 1100 ft 1179 (Cawtawba) TL Turnberry ~300' on left S.R. No. _____

SUBDIVISION NAME St. Andrew's Village LOT NO. 5 SECTION OR BLOCK NO. _____

House ☑ Mobile Home ☐ Business ☐ Other _____

No. Bedrooms 4 w/ Addn No. Bathrooms 3

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area ~20,000 ft²

Soil Characteristics ps clay


Application Rate .35

Topography 4%

Depth to Water Table 74"

Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement ✓ Crawl Space



Plot of System (Not to Scale)

Size of Tank Existing Gals.

Nitrification Field:

No. of Lines 1

Sq. Ft. 345 Linear Ft. 115 + Ex.

Depth of Stone in Lines 12"

Water Supply: Individual ☐ Public ☑ CW

Installed by Richard Abernathy

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY DRH

COMMENTS New deck extension was added to existing deck. The left rear support (deck) post barely missed last original drop bay on initial system.

CERTIFICATE OF COMPLETION BY David R Hanson RS DATE 11/3/92

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR ABJ Construction DATE 4/25/89 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 1100 TL 1179 (Canvasback) TL St Andrews Village ~600' on left S. R. No. _____

SUBDIVISION NAME St Andrews Village LOT NO. 5 SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	clay	
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	.35	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-4%	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4'+	
			Rock or other impervious formations	none obs	

Lot Area 20000 ft²

____ Basement with Plumbing ____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 5
Sq. Ft. 1035 Linear Ft. 345
Depth of Stone in Lines 12"

Water Supply: Individual ( )
Public (✓)
Community

Prop. Line

Installed by Julian Bowles

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: see note for change of layout - 4-21-89 DRH

CERTIFICATE OF COMPLETION BY Andrew Rice DATE 4/25/89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold