07902

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Paul Gargano DATE May 23, '88 PERMIT NO. 4636-97-8797

PHONE: Business _____ Home _____

LOCATION 1100 TR 1179 (Canarbark) TR Woodduck Loop ~ ½ mile on left S. R. No. _____

SUBDIVISION NAME Lakeside Farms LOT NO. 11 SECTION OR BLOCK NO. 1

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 3


Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site ~~Suitable~~ PS Yes (✓) No ( )

Lot Area ~1/2 AC

Character & Porosity of Soil clay
Percolation Rate 35
Topography 4 & 20
Depth to Water Table 44
Rock or other impervious formations none obs.

1000 gal pump tank

✓ Basement with Plumbing ____ Basement without Plumbing ____ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 4
Sq. Ft. 1035 Linear Ft. 345
Depth of Stone in Lines 12"

Water Supply: Individual ( )
Public (✓)
LAKE

Installed by Cam Const.

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DKH

COMMENTS: Alarm on site but not mounted. It was tested and found to be working.

CERTIFICATE OF COMPLETION BY DE Hinson, RS DATE 5-23-88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold