DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

4637-00-6394

Sheet 1 of 1
PROPERTY ID #:
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: David T. Martin Inc APPLICATION DATE 7-15-04
ADDRESS: PO Box 6105 Statesville 28687 DATE EVALUATED: 7-24-04
PROPOSED FACILITY: SFRD 4br PROPOSED DESIGN FLOW (.1949): 440 PROPERTY SIZE: .71
LOCATION OF SITE: Brawley School (R) Blume (L) Beaten Path (L) Vista Bluff PROPERTY RECORDED: yes
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other VISTA BLUFF LOT 6
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L	0-2	wk sbk scl	vfr ss/sp sexp	—	>48	—	—	PS .3
		2-48	mo abk C	fr s/p "					
2	L	0-2	wk sbk scl		—	>48	—	—	PS .3
		2-48	mo abk C	fr s/p sexp					
3	L	0-6	scl		—	>48	—	—	PS .3
		6-24	mo abk C	fr s/p sexp					
		24-48	mo abk C+soap	fr s/p "					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948): UN
EVALUATED BY: CS
OTHER(S) PRESENT: No

COMMENTS: