DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: _____ lot 8 Mcrary _____ PROPERTY RECORDED: _____
WATER SUPPLY: ❑ Private ❑ Public ❑ Well ❑ Spring ❑ Other _____
EVALUATION METHOD: ❑ Auger Boring ❑ Pit ❑ Cut
TYPE OF WASTEWATER: ❑ Sewage ❑ Industrial Process ❑ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-26	LC SAM	fr: SSP	Many Yw Mott SAP Tex				PS .3
		26-98	LCL MSAM	fr: SAP —					
2		0-14	RCL SAM	fr: SSSP					PS .4
		14-46	LSAP WSAM/Mass Structureless	fr: SSSP/NSNP					
3		0-24	LC SAM	fr: SSSP					PS .3
		24-98	RCL MSSM	fr: SSSP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____

0.68 AC.
6
70.00'
60.00'
45.00'
55.00'
37.00'
S 53°27'15" W
S 58°27'42" E
229.07'
0.76 AC
7
265.59'
S 58°27'42" E
0.64 AC.
8
S 58°27'42" E
0.73 AC
9
S 58°27'42" E
242.20'
S 58°27'42" E
0.85 AC.
10
S 58°27'42" E
594.55'
S 58°27'42" E
N 25°45'
N 25°45'
30.78'
C11
C10
38.31'
N 38°57'07" E
142.35'
35.00'
Old Selbock