DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

# SOIL/SITE EVALUATION
## FOR
## ON-SITE WASTEWATER SYSTEM

APPLICANT: Tom Wilson OWNER: ↘ AGENT: __ PHONE: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: 9-2-93
PROPOSED FACILITY: single family residence
PROPERTY SIZE: 0.50 Acres
LOCATION OF SITE: SPRING ACRES LOT 58
WATER SUPPLY: On-Site Well ↘ Comm. Well ___ Public ___ Other ____ EVAL. METHOD: Auger Boring ↘ Pit ___ Cut ___

| PROFILE # | .1940 LANDSCP POS. (%) | HORIZON DEPTH (IN.) | .1941 STRUCTURE/TEXTURE | .1941 MINERALOGY/ CONSISTENCE | .1942 WETNESS COND. | .1944 RESTRICT HORIZONS | .1948 CLASS OF HORIZ | 1943/ 1956 SAPRLT CLASS. | HORIZON LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | shoulder slope 2-4% | 0-12 | clay loam | mfr-mfi | | | | | |
| | | 12-21 | cl/wk med sbk | mvfi | — | — | P | — | 0.3-.35 |
| | | 21-34 | sic/wk med sbk | mfi | — | — | P | — | 0.3 |
| | | 34-42 | sil/wk fn sbk med gran | dsh-ds | >42" | >42" | — | — | — |
| 2 | draw 2-4% | 0-16 | sl/mod med gran | mvfr | | | | | |
| | | 16-23 | cl/mod med granr sbk | mfr | | | | | |
| | | 23-44 | sl/wk fn gran | mvfr (dl) | >42" | >42" | P | — | 0.4 |
| 3 | shoulder slope 2-4% | 0-8 | fsl/mod med gran | mvfr | | | | | |
| | | 8-16 | scl/mod med granr sbk | mfr | — | — | P | — | 0.35 |
| | | 16-34 | c/med-wk med sbk | mfi | — | — | P | — | 0.3 |
| | | 34-44 | sc/wk med granr sbk | mfi | >42" | >42" | P | — | 0.3 |
| 4 | | | | | | | | | |
| 5 | | | | | | | | | |

AVAILABLE SPACE (.1945) ____ SITE CLASSIFICATION (.1948): ____ SITE LONG-TERM ACCEPTANCE RATE: 0.3
EVALUATED BY: A.L. OTHER(S) PRESENT: NONE
COMMENTS: System must be located at front of lot due to landscape position of rear of lot. Bullrush grass growing in and around cutted areas.