DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET 1 OF 1
PROPERTY I.D.#:
PROPERTY RECORDED: YES
COUNTY: Iredell

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Phillip Bertok OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED: 10/14/93
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE: Lot 47 Spring Acres
WATER SUPPLY: On-Site Well ✓ Comm. Well Public Other EVAL. METHOD: Auger Boring ✓ Pit Cut

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	SS	0-4"	gr-SAB / scl	1:1 / fr	—	—	PS	—	.5
		4-24"	SAB / C	1:1 / fi	—	—	PS	—	.4
		24-48"	SAB / scl	1:1 / fr	—	hit some weathered rock at 24-30"	PS	—	.3
2									
3									
4									
5									

AVAILABLE SPACE (.1945): PS-U SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: .3
EVALUATED BY: OTHER(S) PRESENT: Phillip Bertok
COMMENTS: Limited system can be conventional; repair will likely be PPBPS.