DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ *of* ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 16 McCrary Woods PROPERTY RECORDED: _____
WATER SUPPLY: ❑ Private ❑ Public ❑ Well ❑ Spring ❑ Other _____
EVALUATION METHOD: ❑ Auger Boring ❑ Pit ❑ Cut
TYPE OF WASTEWATER: ❑ Sewage ❑ Industrial Process ❑ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-14	SL wGR	fr SSSP					PS .3
		14-36	RC SNG	fri SSP					
		36-52	RCL mSBK	fr SSP					
2		0-17	RC SAND	fr SSSP					PS .3
		17-26	RCL MSBK	fr SSSP common S/A					
		26-48	SCL/CSAPM	fr NSNP					
3	4/0% Dunes 8-4-05	0-26	LSBK C	fr SSSP SE					PS .3
		26-48	C+SAP	FR SS/SP SE					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

RIVERWOOD ROAD
S.R. 1168
(60' ROAD R/W)
C17
C18
C19
C20
S 39°42'23" W
88.55'
81.05'
S 28°20'39" E
308.70'
S 24°59'12" E
336.19'
S 24°59'32" E
286.00'
S 34°12'09" E
280.72'
S 53°27'15" W
60.00'
45.00'
55.00'
37.00'
N 71°50'51" W
131.73'
35' Front Setback
0.76 AC.
15
0.75 AC.
16
0.73 AC.
17
0.79 AC.
18
35' Front Setback
310.00'
Shade Trees
Shade trees
30'±