Inspected 1/29/2002

08775

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Wayne Ervin / Charles Ray Edward Arnold DATE 10/14/88 PERMIT NO. 20B

PHONE: Business _____ Home _____

LOCATION 150 W TL McCrary (1168) TR Riverwood 1st lot on left S. R. No. _____

SUBDIVISION NAME CL and T LOT NO. 1158 SECTION OR BLOCK NO. 10

4637-15-4158

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2-3

Garbage Disposal Unit Yes (✓) No ( )

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Character & Porosity of Soil Clay

Percolation Rate ~.35

Topography 4-8%


Depth to Water Table 4'+

Rock or other impervious formations none obs.

Lot Area _____

_____ Basement with Plumbing Lake _____ Basement without Plumbing _____ No Basement

Pump Tank: 1250 gal.



Plot of System NOT TO SCALE

Size of Tank 1250 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 1035 Linear Ft. 345

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Wayne Ervin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: Cked tanks, pump lines, pump set. Alarm mounted and connected.

CERTIFICATE OF COMPLETION BY Andrew C. Prince DATE 10/14/88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold