...ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-21-01
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 4 Devonshire PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-58 | wksl sd cl | fr sssp sosp | | | | | .3 |
| 2 | | 0-12 | gr brn sd/scl | fr sssp | | | | | .3 |
| | | 12-32 | sdy pcl cl | fr sssp sosp | | | | | |
| | | 32-49 | wk sdy yl scl | fr sssp | | | | | |
| | | | large amount of rock in this pit - probable soil | | | | | | |
| 3 | | 5-20 | wksdy cl | fr sssp | | | | | =3 |
| | | 20-39 | wk sdy w/ inclcl | fr sssp | | | | | |
| | | 39-50 | cl w/ sdy | fr sssp | | | | | |
| | | | large amount of sdy & wk | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| ailable Space (.1945) | | |
| stem Type(s) | | |
| : LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____